


VG-3406 user manual

1. Attached are three replacement molds: 2, 3 and 6PIN (figure 1)

31001: 2Pin

31002: 3Pin

31003: 6Pin



Step 1: loosen the middle screw of the cross screwdriver and replace the number of pins you need (figure 2)

(31001 mold is recommended for processing 34E-03, to avoid pressing to the simple socket around 34E-xx.)



Step 2: after pressing, rotate the direction of Release arrow to loosen VG-3406 (figure 3).

Step 3: place the 34E-XX simple socket, open the cover and press it to the bottom to avoid damaging the cover when working (figure 4)



Step 4: face to yourself at the joint of the VG-3406 hand pressure clamp. Insert the soft line FPC or FFC with a distance of 2.54mm. After the line is aligned, press and press with both hands, and then release by step 2, and so on.



Packing method: Standard carton packing

